## Approved For Release 2001/08/16 : CIA-RDP81B00961R000100170140-3

## SECRET

OSA 3412-64

14 July 1964

MEMORANDUM FOR: Chief, Logistics Services Division

SUBJECT : Safety and Security in Vaulted Area

5B2817

REFERENCE: Kemorandum from Chief, Physical Security

Division, Office of Security, Subject: OSA Area 5B2817, dated 23 June 1964

- 1. There is attached for your information a thermofax copy of the referenced memorandum requesting that certain items be accomplished to meet the minimum safety and security standards for personnel occupying Room 5B2817.
- 2. In view of the attachment, it is requested that your office make the necessary arrangements to have the following items completed within office complex 5B2817:
  - a. Installation of a dome type fire detection system. System to be combination rate-of-rise and set temperature and automatically resettable on both sides.
  - b. The room housing the electronic equipment should be equipped with a master control switch at each principal entrance to disconnect all electrical equipment in case of fire.
  - c. The electrical fans now being used within this office complex should be mounted on the walls to alleviate the possible safety hazard which presently exists.
  - d. Balance the existing Kidde Ultrasonic Alarm System to include the middle room of the suite. Include in this work order the mounting of door contact

138

2011

OSA 3412-64

switches on the two (2) new double doors and the consolidation of the two alarm systems into one (1) single system with monitor unit mounted adjacent to door 5B-2817.

3. If required, OSA Allotment Number 5261-1000 may be cited for any funding necessary.

25X1A

4. Please call extension 7761 for access to the area.

25X1A



Support Division, OSA

ATTACH: a/s

25X1A

OSA:SD: Distribution:

Orig & 1 - Addee

1 - SD/OSA

1 - RB/OSA